



General Description

X-Bond is a specially formulated adhesive stripper. X-Bond will break-down and liquefy cyanoacrylate(instant) and 2-part(catalyst) adhesives. Ideal for use on wood and aluminum frames when removing the mesh. X-Bond works perfectly at removing small drops of adhesive that fall on the mesh during the re-stretching process.

Quick Tip:

For Best Results:
Use a putty knife to quickly scrape and remove dissolved adhesive.

Advantages

- Easy to use - Gel
- Quickly dissolves cyanoacrylate(instant) Adhesives
- Quickly dissolves 2-Part(catalyst) Adhesives
- Non-Hazardous
- Non-Flammable
- Low Odor
- Mesh Safe

Application



Step 1. Apply X-Bond directly to the adhesive. X-Bond will break the adhesive bond in 1-3 minutes*



Step 2. Remove the dissolved adhesive from the surface.



Step 3. Rinse or wipe down the surface.

** Allow to dwell for 20-30 minutes to completely liquefy the adhesive.*

Available in:

1 quart! ! ! 1 gallon! ! ! 5 gallon pail!! !

Prochem™ X-Bond

1850 Wild Turkey Circle - Corona, CA 92880 PHONE (951)735-5511 FAX (951)735-7999 www.ccidom.com