

Product Information Bulletin

Iconowoa Oasis™ Retarder

Wilflex[™] Oasis Retarder is an additive designed to the extend the screen life of Oasis inks.

III Highlights

► Helps extend the screen life of Oasis inks from drying in the screen.

Printing Tips

- Recommended for use with Oasis inks at a rate of 1%, up to 3% max by weight. Additions above 3% may reduce wash fastness of the print.
- ▶← Refer to Oasis base PIR

W Compliance

- Compliant with CPSIA 2008 (Consumer Product Safety Improvement Act) Section 101, Lead Content in Substrates (<100 ppm lead); 16 CFR, Part 1303, Lead in Paint (<90 ppm lead); and CPSIA 2008, Section 108, Phthalates (<0.1% DEHP, DBP, BBP, DINP, DIDP, DNOP).</p>
- ► Non-PVC. Non-Phthalate.

Precautions

- Most substrates are suitable for printing; however, fibers which possess a low surface adhesion (e.g. polypropylene, silk, polyamide or wool) will require special care during drying and cure processes. Test all fabrics for color fixation and wash fastness before starting any production runs
- Perform fusion tests before production. Failure to cure ink properly may result in poor wash fastness, inferior adhesion and unacceptable durability. Ink flash temperatures should be measured on the ink surface using an infrared thermometer sensor. Ink cure temperatures should be measured using a Thermoprobe placed directly in the wet ink film (printed) and verified on the production run substrate(s) and production equipment. It is the responsibility of the printer to determine that the correct ink has been selected for a specific substrate and the application processes meet your customer's standards or specifications.
- -To avoid ink interaction in the image area, verify that the screen mesh is clean of previous ghost images. The image area must be clean and de-hazed
- ► Excess additions of Oasis additives into Oasis inks may adversely affect ink properties.
- ►Containers must maintain air-tight seal when not in use.
- ► NON-CONTAMINATION OF OASIS INKS: Do not add or mix non-Oasis inks, additives or extenders with Oasis inks. All buckets, palette knives, stirring apparatus, squeegees, flood bars and screens must be cleaned properly and free of phthalates and PVC containing inks. Non-phthalate emulsions and pallet adhesives must be used. Failure to follow these precautions may cause phthalate contamination in violation of consumer protection laws and regulations
- Any application not referred in this product information bulletin should be pre-tested or consultation sought with Wilflex Technical Services Department prior to printing.
- ▶ Email: techserviceswilflex@polyone.com



Oasis Additives Add into Oasis inks at a rate of 1%

Do not exceed 3% max. *All percentages listed at % by weight.



Storage 37-104°F (3-40°C). Use within one year of manufacture date. Keep containers sealed at all times.



Clean Up Warm Soap Water (Tap) Gentle Pressure



MSDS: www.polyone.com or Contact your local CSR.


www.wilflex.com/pib

PolyOne Wilflex™ inks by PolyOne. ©2013 PolyOne Corporation All Rights Reserved. Effective 02/04/2013. Not all Wilflex products are available in every country. The information in this publication is based on information and experience believed reliable. Since many factors may affect processing for an application, processors must carry out their own tests and experiments to confirm suitability for intended use. You must make your own determination of suitability for your intended use and environmental acceptability, the safety and health of your employees, and purchasers of your product.





CALL US 888-578-5713



Opacity N/A

Recommended Parameters

Flash N/A Gloss N/A Printability N/A

Bleed Resistance N/A Smooth Surface N/A



Fabric Types Refer to Oasis base PIB.



Tension: Refer to Oasis base PIB.

Squeegee

Mesh



Edge: Refer to Oasis base PIB. Stroke: Refer to Oasis base PIB. Angle: Refer to Oasis base PIB.



Water-Resistant Stencil

Counts: Refer to Oasis base PIB.

Direct: Refer to Oasis base PIB. Capillary/Thick Film: N/A Off-Contact: Refer to Oasis base PIB. Emulsion-over-Mesh: Refer to Oasis base PIB.



Flash & Cure Temperatures

Flash: Refer to Oasis base PIB. Cure: Refer to Oasis base PIB.

Pigment Loading

WPC: N/A



