

## **ProChem™ X-Bond**

Adhesive Debonder / Remover - Gel

**Quick Tip:** 

adhesive.

For Best Results: Use a putty knife to

quickly scrape and remove dissolved

## **General Description**

X-Bond is a specially formulated adhesive stripper. X-Bond will breakdown and liquefy cyanoacrylate(instant) and 2-part(catalyst) adhesives. Ideal for use on wood and aluminum frames when removing the mesh. X-Bond works perfectly at removing small drops of adhesive that fall on the mesh during the re-stretching process.

## **Advantages**

- · Easy to use Gel
- Quickly dissolves cyanoacrylate(instant) Adhesives
- Quickly dissolves 2-Part(catalyst) Adhesives
- Non-Hazardous
- Non-Flammable
- Low Odor
- Mesh Safe

## **Application**



**Step 1**. Apply X-Bond directly to the adhesive. X-Bond will break the adhesive bond in 1-3 minutes\*



**Step 2.** Remove the dissolved adhesive from the surface.



**Step 3.** Rinse or wipe down the surface.

\* Allow to dwell for 20-30 minutes to completely liquefy the adhesive.



1850 Wild Turkey Circle - Corona, CA 92880 PHONE (951)735-5511 FAX (951)735-7999 www.ccidom.com



